															rage i oi	
1-BASIC			National Fire Incident Reporting System													
FDID	DID STATE		INCIDENT REPORT			INCIDENT NUMBER EXP		NO	VERSION		STATION	FD B	ΟX	DISTRICT		
38005	CA	SAI	SAN FRANCISCO FIRE DEPARTM			2502	1907	0		V00		07	545	6	District 06	
INCIDENT DATE	ALARM TIN	E ARF	RIVALTIME	CLEAR TIME	FIRST UNIT	г	INCIDEN	NT COMMANDER		MU		TUAL AID	MULT	MULTI-AGENCY INC. NO		
02/10/2025	02/10/25 04:	58 02/1	10/25 05:01	02/10/25 07:2	_	Joyce Stephen			n		N None					
LOCATION TYPE				INCID	/ LOCATIO	LOCATION			APARTME	NT	ZIP CODE			ALARMS		
1 Street address				9	STREET	TREET					94110 1					
INCIDENT TYPE				ACTIONS TAKEN												
111	Building fire		11 Extir	guishment by fi	re service perso	nnel										
		<b>RESO</b>	URCES	E	STIMATED I	LOSSES A	ND VAL	UES				CASUAI	TIES.			
	APPARATU	S PEI	RSONNEL	ONNEL LOSSES P				100,000				DEATHS		П	INJURIES	
SUPPRESSION	9		33		CONTENTS		20,000			FIRE SERV	/ICE	E 0			0	
EMS	2		3	VALUE	PROPERTY					CIVILIA	N	(			0	
OTHER	2		3	CONTENTS												
MIXED USE PROPERTY			P	ROPERTY USE		DETECTOR					HAZARDOUS MATERIALS RELEASE					
			429 Multifamily dwelling													
2-FIRE																
PROPERT			RTY DETAI	TY DETAILS			ON-SITE MATERIALS					STORAGE USE				
# RESIDENTIAL UNITS 28			N	NOT RESIDENTIAL?		е										
# BUILDING INVOLVED			N	NO BLD INVOLVED?												
# ACRES BURNED				LESS THAN ONE? False												
AREA OF ORIGIN				HEAT SOURCE			ITEM FIRST IGNITED					TYPE OF MATERIAL FIRST IGNITED				
20 Function areas, other				UU Undet			UU Undetermined				_					
CAUSE OF IGNITION			_			CONTRIBUT	NTRIBUTING IGNITION				_	HUMAN FACTORS FOR IGNITION				
U Cause undetermined after investigation			1	UU Undet	_	MODEL				_	N None					
AGE IN	IF EQUIPMENT OLVED IN IGNITION			TYPE		E	MODEL	MODEL SE		ERIAL NO Y		EQUIPMENT POWER			POWER	
SEX				EQUIPMENT PORTABILITY			MOBILE PROPERTY T			VDE	MOBILE PROPERTY MAKE					
FIRE SUPPRESSION FACTORS			+	EQUIPMENT PORTABILITY			WOBILE PROPERTY			IPE	+	MODILE PROPERTY MAKE				
			м	MOBILE PROPERTY INVOLVED			MODEL YEAR		VEAR	LICENSE	DI ATE	NO ST	ATE		VIN	
				MODILE PROPERTY INVOLVED			MODEL TEAM			LICENCE	LAIL	110 01	-		****	
3-STRUCTUR	C CIDC															
STRUCTURE TYPE			BUILDING STATUS		STOR	RIES ABOVE				AL SQ FT	LENG	TH WID		_	BELOW GRAD	
1 Enclosed building			2 In normal use			4				18120		┵	2	_	VDE	
FIRE DAMAGE  2 Confined to room of origin MINOR			STORIES DAMAGED BY FLAME SIGNIF. HEAVY EXT			NO SPREAD? CON			RIB ITEM			CONT	(IB T	YPE		
		TYPI				RATION	raise	EFFECTIVE		NESS		FAILURE REASON				
		1 Smo				or operated	2 Detect	2 Detector alerted occupa								
AES PRESENCE		1 01110		TYPE AES OPE			Z DOIGGE	AES FAIL		-		#SPRINK. HEADS				
1 Present				Wet-pipe sprinkler syst 3 Fire too small to								"O' TANK HEADO				
1S - NARRAT										l 01						
		1 11 11	·00·0= 2/40	/2025 of 4004 b	oure o "full De-	" occienmen	two dies	tohod to #	o che	Joyce Ste		ort of "DD	coor flore	00.00	oming out" At	
Keehn, Theodore 2 approximately 053 frame structure wh was estimated by l	3 hours, this invi ich was occupie	estigative d during t	unit was "S <sub>l</sub> he initiation	pecial Call" dispa of the fire. The	atched to condu fire involved a s	ict an origin a single location	nd cause ir in a lightw	nvestigation ell on the 2	n. This 2nd floo	s is a multi-st or. The fire v	ory, rea	sidential a stained to	oartment b he area o	ouildir of origi	ng, wood jin. Damage	

Disclaimer: Entries contained in this report are intended for the sole use of the State Fire Marshal. Estimations and evaluations made herein represent "most likely" and "most probable" cause and effect. Any representation as to the validity or accuracy of reported conditions outside the State Fire Marshal's office is neither intended nor implied.

250-078-997. BFI Sergeant was notified of the fire. This fire was extinguished without reported complications or injury. A naked male subject was detained on the scene for 5150 WIC

and transported to

The cause of the fire is undetermined